Work Order ID 53551 November 9, 2009 10:02:08 AM			I I I I I I I I I I I I I I I I I I I								Page 1
Item ID:	D2989-3			Accept				s	etup Star	t III	
Revision ID:	D						 				
Item Name:	Rib								Stor		
Start Date:	09/11/2009	Start Qty: 2.00			Cust Item II):					
Required Date:	13/11/2009	Req'd Qty: 2.00			Customer:						
Reference:	•		1144114 11511441								
Approvals:	Process Plan	n: <i>B</i> /	Date:09-11-9	Tooling:	Da	te:	_	R	lun Star		
	QC:		Date:	SPC (Y/N):	Da	te:			Stoj		
Sequence ID/ Work Center I	D	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revi	ision Nbr									
D2989	Rev	D									
100 Large Fab		Large Fab		0.00				(2)			
Large Fab		1- pick D31	66-3 cut D2989-3 to length er dwg D2989□2- remove id								
110 		QC5- Inspect part comp	leteness to step on W/O	0.00	07/11/16			(HŽ)	4		_
QC		Memo		0.00					1		

120

Quality Control

Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

0.00

PD 09.11.16____

Work Order ID 53551

November 9, 2009 10:02:08 AM



Page 2

Item ID:

D2989-3

Revision ID: D

Rib Item Name:

Start Date:

09/11/2009

Start Oty: 2.00

Required Date: 13/11/2009

Req'd Qty: 2.00

Accept



Setup Start



Cust Item ID:

Customer:

Reference:

Δ.	mr	wo	c.	

Process Plan:

QC21- Final Inspection - Work Order Release

Date: Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Run Start

Stop



Sequence ID/

Operation Work Center ID Description

QC:

130

Quality Control

Memo

0.00

0.00

Draw Number

Rev.

Date:

Draw Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

Picklist Print

November 9, 2009 10:02:12 AM

Work Order ID: 53551

Parent Item:

D2989-3RevD

Parent Item Name: Rib

Comments:



Start Date: 09/11/2009

Required Date: 13/11/2009

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
D3166-3RevA1		Manufacture	d No			100	Each	6.2421	0.1684			



Basket Hoop

Warehouse	Loc Oty	Loc Code	•
Location			
Main Warehouse			
WA	6.2421		
50033	0.0527		
50618	0.1894		,
52058	6		64.168A

Page 1

D2989-043 BASKET LID ASSEMBLY (MESH SHOWN LOCALLY FOR CLARITY) D2989-041 BASKET LID ASSEMBLY (MESH SHOWN LOCALLY FOR CLARITY) SHOP COTY RETURNIO ENGINEEDO O UNCONTROLL . CCC. SUBJECT TO AMIL TO A ... WITHOUT WORK (NO. 5355) Port 09-11-9 NOTES: 1) MATERIAL: N/A

	ITEM	QTY -041	QTY -043	P/N	DESCRIPTION
Ì	1	Х		D2989-041	BASKET LID ASSEMBLY
[2		Х	D2989-043	BASKET LID ASSEMBLY
-				DOFOC	LADEL DIATE
ŀ	3	1	ļ	D2506	LABEL PLATE
-	4	1		D2512-7	RIB
1	5	2		D2581	MOUNTING BRACKET
	6		1	D2989-3	RIB
ĺ	. 7		1	D2989-4	RIB
ĺ	8		2	D2989-5	RIB
ı	9	2		D2989-13	RIB
-	10	2	1	D2989-17	RIB
-	11	2		D2989-19	RIB
	12		2	D3182-1	HINGE
1	13		2	D3442-3	SHIM
	14		1	D3827-041	RIB ASSY (INBOARD)
	15	1		D3832-3	MESH, BASKET LID
	16		1_	D3832-5	MESH, BASKET LID
	17	2		D3833-3	MESH, LID END
	18		2	D3833-5	MESH, LID END
	19	1		D3836-041	RIB ASSY (BASKET LID, LH)
	20	1		D3836-042	RIB ASSY (BASKET LID, RH)
	21		1	D3838-041	RIB ASSY (BASKET LID, LH)
1	22		1	D3838-042	RIB ASSY (BASKET LID, RH)
-	23	1		D3852-041	RIB ASSEMBLY
	24	_1		D3852-042	RIB ASSEMBLY

REVISED -041/-043 PARTS LISTS AND ADDED "ITEM" COLUMN TO PARTS LIST (ZN D3-1); D3836-041 REPLACES D2989-10; D3835-041 REPLACES D2989-10; D3835-041 REPLACES D2989-10; D3835-042 REPLACES D2989-17; D3835-042 REPLACES D2989-17; D3835-042 REPLACES D2989-2; REMOVED D2327-3 (NOW INSTALLED ON D3836 DWG), D2989-11; D3852-041 REPLACES D2989-2; REMOVED D2327-3 (NOW INSTALLED ON D3836 DWG), D3936-100; D2989-110; D7980; D2989-110; D7980; D2989-110; D7980; D2989-110; D7980; D2989-110; D7980; D2989-110; D7980; D7980 08.09.24 FRAME MATERIAL WAS 0.060 WALL; MESH MATERIAL UPDATED; DRAWING TRANSFERED TO "B" FORMAT AND CURRENT DRAFTING STANDARD AJS 08.06.20 ADD SHIM UNDER HINGES, UPDATE LID DIMENSIONS PH 05.06.07 Α NEW ISSUE DS 00.10.27 REV. DESCRIPTION BY DATE

DESIGN	ЦS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA				
DRAWN	1					
CHECKED	ASS	DRAWING NO.	REV. D			
MFG. APPR.		D2989	SHEET 1 OF 5			
APPROVED	700	TITLE	SCALE			
DE APPR.	-#	BASKET LID ASSEMBLY	NTS			
DATE 08.0	09.24	COPYRIGHT © 2000 BY DART AEROSPACE LTD THIS DOCUMENT IS HIGHTE AND COMPONENTLY, HIGH IS SUPPLIED ON THE EXPRESS CONSTITUTION THAT IT IS NOT TO BE LIKED FOR ANY PURPOSE OF COPYRIGHD COMPANIONAL TO LAW OTHER PRESCRIPTION.				

1) MATERIAL: NIA
2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT AS INDICATED PER DART QSI 005 4.4
SPRAY PAINT INSIDE SURFACE BLACK PRIOR TO APPLYING ANTI-SKID
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) RDFG4 (MADD EDGES O 034 MAX 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX 6) IDENTIFICATION: N/A 7) WEIGHT: D2989-041 = 26.50 lbs; D2989-043 = 15.50 lbs 8) WELD PER DART QSI 004

8







